

RECALL NOTICE

SR SUNTOUR North America, Inc. Announces Recall of
M3010 (24" and 26"), M3020 (24" and 26"), M3030 (26", 27.5" and 29"),
NEX (700 c), and XCT (20", 26", 27.5" and 29")
Bicycle Forks



Figure: Singular fixing bolt version
(Right Side Only)




Figure: Multiple fixing bolt versions
(Right and Left Sides)

Hazard: The fixing bolt can break, causing the lowers to separate from the stanchion posing a fall hazard.

Recalled Product: SR Suntour bicycle forks, M3010 (24" and 26"), M3020 (24" and 26"), M3030 (26", 27.5" and 29"), NEX (700 c), and XCT (20", 26", 27.5" and 29") made between November 1, 2014 and January 27, 2015. Serial Numbers K*141101 through K*150127.

Remedy: Consumers should stop using bicycles with these forks and return them to the store where they were purchased for inspection and possible repair.

For more information:

1-888-820-8458

Monday through Friday 9:00 a.m. to 6:00 p.m. (Central Time)

www.srsuntour-cycling.com

This recall is being conducted in cooperation with the
U.S. Consumer Product Safety Commission

Post Until October 1, 2015